

Field Verification Report for Cox Energy Industrial Coatings &
Employee: Bauer, Claude William
Candidate ID: cb-111702-01
TWIC Card: No Card
Date: 3/4/2025 1:04:00 PM CST

Individual Verifying OQ Signature:	
Individual Verifying OQ Print Name:	

Notice: Personnel qualifications identified on this report are valid only for TC Energy.

To verify the candidate's identity, please compare his/her government issued ID for the following items:

- 1. Photo
- 2. Name
- 3. Date of Birth

The candidate's first and last initials and date of birth are the candidate id listed below.

If you have any questions, please call Veriforce at 800.426.1604

Task Identity	Task Desc	Qualification Date	Expiration Date (CST)	ID Verified	Verified By	Verified Date
007	Operate Valves	6/23/2023	6/23/2026			
208	Plastic Pipe Joining: Butt Fusion	12/31/2024	12/31/2025			
209	Plastic Pipe Joining: Mechanical Joining	12/31/2024	12/31/2025			
210	Plastic Pipe Joining: Electrofusion Joining	12/31/2024	12/31/2025			
325	Installation of Above Ground Pipe	8/8/2023	8/8/2026			
401	Examination of Buried Pipelines When Exposed	7/5/2023	7/5/2026			
404	Protection of Coating When Backfilling and From Below Ground Supports	6/26/2023	6/26/2026			



Field Verification Report for Cox Energy Industrial Coatings &
Employee: Bauer, Claude William
Candidate ID: cb-111702-01
TWIC Card: No Card
Date: 3/4/2025 1:04:00 PM CST

Individual Verifying OQ Signature:	
Individual Verifying OQ Print Name:	

Task Identity	Task Desc	Qualificatio	Expiration	ID Verified	Verified By	Verified Date
405	Protection of Coatings From Above Ground Structures	8/8/2023	8/8/2026			
407	Perform Cathodic Protection Survey	6/26/2023	6/26/2026			
409	Inspect Interference Bonds	6/26/2023	6/26/2026			
411	Inspect/Test to Assure Electrical Isolation is Adequate	6/26/2023	6/26/2026			
412	Install CP Leads on Pipeline Using Exothermic Weld	6/26/2023	6/26/2026			
414	Inspect for Internal Corrosion Whenever Pipe is Removed	7/5/2023	7/5/2026			
417	Atmospheric Corrosion Monitoring	7/5/2023	7/5/2026			
419	Cathodic Protection Potential Measurement	6/26/2023	6/26/2026			
420	Soil Resistivity	6/26/2023	6/26/2026			
421	Measurement of Depth of Pitting with Pit Gage	6/26/2023	6/26/2026			
426	Inspect Pipe Coating with Holiday Detector	7/5/2023	7/5/2026			
428	Pin Brazing to Install CP Leads on Pipeline	8/8/2023	8/8/2026			
431	Install Cathodic Protection Electrical Isolation Devices	8/8/2023	8/8/2026			
435	Measure and Identify Mechanical Damage on Installed Pipe and Components	8/14/2023	8/14/2026			
436	Perform Close Interval Survey	8/10/2023	8/10/2026			
480	Apply Approved Coating by Hand Application	7/5/2023	7/5/2026			



Field Verification Report for Cox Energy Industrial Coatings &
Employee: Bauer, Claude William
Candidate ID: cb-111702-01
TWIC Card: No Card
Date: 3/4/2025 1:04:00 PM CST

Individual Verifying OQ Signature:	
Individual Verifying OQ Print Name:	

Task Identity	Task Desc	Qualificatio	Expiration	ID Verified	Verified By	Verified Date
482	Apply Approved Coatings by Mechanical Spray and Hand Application Methods	7/5/2023	7/5/2026			
484	Apply Approved Coatings by Wrap Application	7/5/2023	7/5/2026			
501	Conduct a Pressure Test	8/8/2023	8/8/2026			
502	Conduct Pressure Test on Pipe that is to be Operated at a Pressure <100 psig	8/8/2023	8/8/2026			
605	Locate Line/Install Temporary Marking of Buried Pipeline	6/22/2023	6/22/2026			
606	Locate and Mark Submerged Pipelines	8/22/2023	8/22/2026			
608	Damage Prevention for Blasting Near a Pipeline	8/10/2023	8/10/2026			
611	Hot Tap (Steel Pipe)	6/22/2023	6/22/2026			
613	Purge Pipeline Facilities With Gas	6/22/2023	6/22/2026			
614	Purge Pipeline Facilities With Air or Inert Gas	6/22/2023	6/22/2026			
616	Atmospheric Monitoring during Hot Work Operations	8/14/2023	8/14/2026			
617	Locate Buried Facilities with an Electro-magnetic Device	6/22/2023	6/22/2026			
619	Damage Prevention during Vacuum Excavation	6/22/2023	6/22/2026			
621	Provide or Assure Adequate Pipeline Support during Operator Initiated Excavation Activities	8/14/2023	8/14/2026			
661	Launching and/or Receiving Internal Devices (Pigs)	8/14/2023	8/14/2026			



Field Verification Report for Cox Energy Industrial Coatings &	
Employee: Bauer, Claude William	
Candidate ID: cb-111702-01	
TWIC Card: No Card	
Date: 3/4/2025 1:04:00 PM CST	

Individual Verifying OQ Signature:	
Individual Verifying OQ Print Name:	

Task Identity	Task Desc	Qualificatio	Expiration	ID Verified	Verified By	Verified Date
701	Patrolling Pipeline and Leakage Survey without Instrument	6/23/2023	6/23/2026			
703	Placing/Maintaining Line Markers	6/23/2023	6/23/2026			
704	Permanent Field Repair by Grinding	6/23/2023	6/23/2026			
707	Permanent Field Repair Using Bolt-On Clamp/Sleeve	8/8/2023	8/8/2026			
713	Test/Maintain Gas Detection and Alarm Systems	6/23/2023	6/23/2026			
716	Inspect, Maintain, and Operate Valves	6/23/2023	6/23/2026			
902	Field Bending of Pipe	6/23/2023	6/23/2026			
903	Directional Drilling and/or Boring	6/23/2023	6/23/2026			
908	Installation of Cathodic Protection	6/23/2023	6/23/2026			
TC-622	Cold Cutting the Pipe (Mechanical)	8/22/2023	8/22/2026			